

table of contents

Section		Page
1	GENERAL DESCRIPTION	1-1
	1.1 General	1-1
	1.2 Reference Data	1-1
	1.3 Transistor and Diode Complement	1-1
	1.4 Fuse Complement	1-2
	1.5 Battery Complement	1-2
2	INSTALLATION	2-1
	2.1 Unpacking	2-1
	2.2 Preparing the Amplifier for Operation	2-1
	2.3 Permanent Installation	2-2
	2.4 Multiple Input	2-2
	2.5 Input Power Change	2-2
3	OPERATION	3-1
	3.1 Setting Up for Remote Operation	3-1
	3.1.1 Connections	3-1
	3.1.2 Prebroadcast Adjustments	3-1
	3.1.2.1 Setting Line Level	3-1
	3.2 Operating Procedures	3-2
	3.2.1 Broadcast Program	3-2
	3.2.2 Public Address Operation	3-2
	3.2.3 Talk Back with One-Line Operation	3-2
	3.2.4 Emergency Switch to Line 2	3-2
	3.2.5 Emergency Switch to Battery Operation	3-2
	3.3 Description of Operating Controls	3-2
	3.3.1 Faders	3-2
	3.3.2 MASTER Gain Control	3-2
	3.3.3 TONE	3-2
	3.3.4 HEADSET LEVEL	3-2
	3.3.5 PA Level	3-2
	3.3.6 OUTPUT Switch	3-2
	3.3.7 VU METER Control and Meter	3-2
	3.3.8 VU Lamp	3-3
	3.3.9 Power Switch	3-3
	3.3.10 Line Monitor Jack	3-3
	3.3.11 Program Monitor	3-3
	3.3.12 Multiple Jack	3-3
	3.3.13 A-C Operation Pilot Lamp	3-3
4	PRINCIPLES OF OPERATION	4-1
	4.1 Mechanical Details	4-1
	4.2 Electrical Details	4-1
	4.2.1 General	4-1
	4.2.2 Audio Amplifier	4-1
	4.2.3 VU Meter	4-2
	4.2.4 Tone Oscillator	4-2
	4.2.5 Power Supply	4-2

table of contents (cont)

Section		Page
5	MAINTENANCE	5-1
5.1	General	5-1
5.2	Test Equipment	5-1
5.3	Transistor Replacement	5-1
5.4	Resistance and Voltage Measurements	5-2
5.4.1	General	5-2
5.5	Fuse	5-2
5.6	Component Parts Replacement	5-2
5.6.1	General	5-2
5.6.2	Special Tools	5-2
5.6.2.1	Soldering Iron	5-2
5.6.2.2	Pin-Nosed Pliers	5-2
5.6.3	Procedure	5-2
5.7	Servicing Transistor Circuits	5-3
5.7.1	General	5-3
5.7.2	Test Equipment	5-3
5.7.2.1	Transformerless Power Supplies	5-3
5.7.2.2	Line Filter	5-3
5.7.2.3	Low Sensitivity Multimeters	5-6
5.7.2.4	Power Supply	5-6
5.7.3	Electric Soldering Irons	5-6
5.7.3.1	Leakage Current	5-6
5.7.3.2	Iron Size	5-6
5.7.4	Servicing Practices	5-7
5.7.4.1	Heat Sink When Soldering	5-7
5.7.4.2	Removal of Transistors from Operating Circuits	5-7
5.7.4.3	Plug-In Transistors	5-7
5.7.4.4	Resistance Measurements in Transistor Circuits	5-7
5.7.4.5	Power Transistor Heat Sinks	5-7
5.7.4.6	Test Prods	5-7
5.7.5	Trouble Shooting	5-7
5.7.5.1	Ohmmeter Test of Transistors	5-7
6	PARTS LIST	6-1
7	ILLUSTRATIONS	7-1

list of illustrations

Figure		Page
1-1	212Z-1 Remote Amplifier in Carrying Case and 212Z-1 Block Diagram (C79-09-P) (C79-13-3)	1-0
2-1	212Z-1 Remote Amplifier, Connections	2-1
2-2	115V/230V Input Power Change, Schematic Diagram (C79-15-3)	2-2

list of illustrations (cont)

Figure		Page
3-1	212Z-1 Remote Amplifier, Controls (C79-05-P)	3-1
4-1	Output Circuits, Simplified Schematic (C97-02-4)	4-0
5-1	Voltage Measurements, Preamplifier Board (C79-11-4)	5-3
5-2	Voltage Measurements, Amplifier Board (C79-12-3).	5-4
5-3	Voltage Measurements, Oscillator Board (C79-10-3)	5-5
5-4	212Z-1 Gain Chart (C79-14-3)	5-6
7-1	212Z-1 Remote Amplifier, Bottom View (C79-08-P).	7-1
7-2	212Z-1 Remote Amplifier, Bottom Open, Boards Removed (C79-06-P)	7-2
7-3	Power Supply, Top Open View (C79-04-P)	7-3
7-4	Power Supply, Side Open View (C79-03-P)	7-3
7-5	212Z-1 Remote Amplifier, Complete Schematic	7-5

list of tables

Table		Page
5-1	List of Test Equipment	5-1